

External Wiring Drawing of Panel

MAN014.DOC

- # 3 Phase Supply to be Given Via Plastic 3 Phase 4 Wire Plug/Socket.
- # All 4 Wires R, Y, B, and Neutral N to be Properly Connected as in Socket.
- # Earth Metal Strip Given Near Socket to be Connected to a Good Earth.

- # External "N" or Neutral Wiring can Be Terminated to the Main N Terminal.
- # Terminals to be fixed near Solenoids and wire ended external items.
- # 5 Amps Grey wires with Lugs and Ferroles for all Solenoids.
- # 4 Core 440V Wire for all 3 Phase Motors.
- # Cable Ties and Supports to be used for proper wiring.
- # Rubber Grommets and PVC Armor for all wires where Required.

